


SPEED DATA ANALYSIS

Location



ROSEDALE AVENUE
PARKSIDE AVENUE
Latitude: 40.760745
Longitude: -74.399256



Analysis Time Period



Start	End
7/8/2021	7/18/2021
1:26 PM	12:03 PM

Vehicles Analyzed



26,412

Peak Time of Violations



7/9/2021
12:26 PM

Speed Limit



25

Enforcement Tolerance



10

Total Enforceable Violations



900

% Enforceable Violations



3%

Average Speed



27

Fastest Speed



57

SPEED DATA ANALYSIS

Slowest Speed

85th Percentile Speed



8



32

Enforcement Rating

LOW

Speed Enforcement Evaluator

Location

ROSEDALE AVENUE

Closest Cross Street

PARKSIDE AVENUE

GPS

Latitude: 40.760745
Longitude: -74.399256

Analysis Dates

Start: 7/8/2021
End: 7/18/2021

Equipment Used


JAMMAR RADAR RECORDER

Installed By


CPL. DIROCCO

Total Percentage of Enforceable Violations


Posted Speed Limit 25 MPH
Enforcement Tolerance 10 MPH
Enforcement Limit Greater than 35 MPH



Percent Speeding: 3%
Rating: Low



Percent Speeding: 2%
Rating: Low



Percent Speeding: 5%
Rating: Low

Vehicle Totals - Combined

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	1	118	427	484	769	2271	6278	8135	4946	2084	671	229
85th Percentile: 31.9													

Vehicle Totals - West, 1

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	0	55	102	114	384	1032	3124	3866	2199	721	145	40
85th Percentile: 30.9													

Vehicle Totals - East, 2

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	1	63	325	370	385	1239	3154	4269	2747	1363	526	189
85th Percentile: 31.9													